


ERA26LA057

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site (Courtesy of FAA)



Photograph 2 - Lower External Longeron Damage (Courtesy of FAA)