



Investigator David Lewis
Aviation Accident Investigator
AS-Eastern Region

Date: December 11, 2025

Subject: ERA26LA057, Interview with Pilot

Contact: [REDACTED], Flight Instructor

An interview was conducted with Flight Instructor [REDACTED] to determine whether any mechanical issues were present with the landing gear system of aircraft N441HG. Instructor [REDACTED] reported that he did not hear the gear warning horn during the landing sequence. Witness statements suggested the landing gear was not extended prior to landing. Instructor [REDACTED] acknowledged that he failed to lower the landing gear before touchdown. A subsequent gear swing confirmed that the landing gear system was operating normally.