

ERA26LA058

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Side View showing damage to wing and aileron (Courtesy of FAA)



Photograph 2 - Closeup of damage to left wing and aileron (Courtesy of FAA)