

ERA26LA060

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left-hand front view showing damage to wings (Courtesy of Airport Authority)



Photograph 2 - Right-hand front view showing damage to landing gear (Courtesy of Airport Authority)



Photograph 3 - Section of perimeter fence impacted by the aircraft (Courtesy of Airport Authority)



Photograph 4 - Left-hand rear view showing damage to wings (Courtesy of Airport Authority)



Photograph 6 - Airport overview of accident location (Courtesy of Airport Authority)