

ERA26LA074

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front Left of Airplane (Courtesy of FAA)



Photograph 2 - Engine Mount Damage (Courtesy of FAA)



Photograph 3 - Left Wing Spar Damage (Courtesy of FAA)



Photograph 4 - Nose Landing Gear Damage (Courtesy of FAA)