

ERA26LA075

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N656B Immediately after Accident in Redwater Lake (Courtesy of Owner)



Photograph 2 - Left-Wing Leading Edge Damage Shown During Recovery (Courtesy of FAA)



Photograph 3 - Left Wing Strut Buckled (Courtesy of FAA)



Photograph 4 - Propeller, Fuselage, Windshield and Wing Strut Damage (Courtesy of FAA)