

ERA26LA082

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of tail showing damage (Courtesy of Pilot)



Photograph 2 - Close up of damage to left side of horizontal stabilator (Courtesy of Pilot)



Photograph 3 - Close up of damage to left side of horizontal stabilator (Courtesy of Pilot)