

ERA26LA088

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overview of the airplane at the accident site. (Courtesy of FAA)



Photograph 2 - View of damage to the right wing leading edge. (Courtesy of FAA)



Photograph 3 - View of damage to the right wing root. (Courtesy of FAA)