


ERA26LA099

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Rans S-21, N88WL (Courtesy of Owner)



Photograph 2 - Left side of fuselage (Courtesy of Owner)



Photograph 3 - Right side of fuselage (Courtesy of Owner)



Photograph 4 - Broken frame on left side of fuselage (Courtesy of Owner)