

ERA26LA103

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Frontal View of the Airplane on the Ramp Note the damaged lower Propeller Blade (Courtesy of FAA)



Photograph 2 - View of the Bottom Fuselage Showing Structural Buckling Damage near Fuselage Station 17 (Courtesy of FAA)



Photograph 3 - View of the Bottom Fuselage Showing Structural Buckling Damage Adjacent to Lower Nose Gear Fitting, Near Fuselage Station 0 (Courtesy of FAA)



**Photograph 4 - View of the Cockpit Showing Buckling of Floor on Pilot and Co-Pilot Locations
(Courtesy of Operator)**



Photograph 5 - Close-Up View Showing Buckling Damage to Pilot's Side Floor (Courtesy of Operator)



Photograph 6 - Close-Up View Showing Buckling Damage to Co-Pilot's Side Floor (Courtesy of Operator)