

ERA26LA122

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Helicopter and Impacted Hangar (Courtesy of Mr. Dickerson)



**Photograph 2 - View of the helicopter after being upright and main rotor blades removed
(Courtesy of Mr. Dickerson)**



Photograph 3 - View of the Impacted Hangar and Area Where Helicopter was Located at Start of Liftoff. Arrows Point to Marks From Both Skids (Courtesy of Mr. Dickerson)