

ERA26LA123

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident with fuselage damage at the step and across to the other side of the belly. (Courtesy of FAA)



Photograph 2 - Right side fuselage damage. (Courtesy of FAA)



**Photograph 3 - Aft view of airplane with damage to vertical stabilizer and rudder.
(Courtesy of FAA)**



Photograph 4 - Left wing and tip damage. (Courtesy of FAA)