

ERA26LA138

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Forward Quartering View of the Inverted Glider at the Accident Site. Note the Partial Chordwise Fracture of the Right Wing (Courtesy of FAA)



Photograph 2 - Right Forward Quartering View of the Inverted Glider at the Accident Site. Note the Partial Chordwise Fracture of the Right Wing (Courtesy of FAA)