

ERA26LA158

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Impact damage noted to windshield and roof structure (Courtesy of FAA)**