

ERA26LA176

INVESTIGATION PHOTOGRAPH




Photograph 1 - Main Wreckage (Courtesy of Pilot)




Photograph 2 - Oil Spray (Courtesy of Pilot)



Photograph 3 - Oil Line Attached With Clamp at Oil Pump Fitting (Courtesy of FAA)



Photograph 4 - Separated Oil Line And Oil Cooler Fitting (Courtesy of FAA)



Photograph 5 - Close-up of Oil Cooler Fitting (Courtesy of FAA)