

ERA26LA185

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Landing gear tracks in the ground leading up to airplane accident location.
(Courtesy of FAA)**



Photograph 2 - Left front view of airplane showing collapsed nose gear. (Courtesy of FAA)



Photograph 3 - View of broken engine mount. (Courtesy of FAA)