

ERA26LA187

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of tire marks approaching the PAPI lights. (Courtesy of FAA)



Photograph 2 - Overview of the accident airplane. (Courtesy of FAA)



Photograph 3 - View of damage to the right horizontal stabilizer. (Courtesy of FAA)