

ERA26LA201

INVESTIGATION PHOTOGRAPHS



**Photograph 1 -Aft view of airplane showing damage to right wing root.
(Courtesy of FAA)**



**Photograph 2 - Close up view of right damaged wing root.
(Courtesy of FAA)**



**Photograph 3 - View of fuel selector behind seat in the off position.
Shown with a red arrow pointing to it.
(Courtesy of FAA)**