

ERA26LA228

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Nose landing gear and lower forward fuselage damage (Courtesy of FAA)



Photograph 2 - NLG tunnel damage (Courtesy of FAA)



Photograph 3 - Forward fuselage structure damage (Courtesy of FAA)