

ERA26LA237

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Landing Gear Impressions Off Left Side of Runway (Courtesy of FAA)



Photograph 2 - Right Main Landing Gear Fairing Scrape Across Taxiway



Photograph 3 - Right Main Landing Gear Separated Fairing (Courtesy of FAA)



Photograph 4 - Landing Gear Grass Impressions Toward VASI Light (Courtesy of FAA)



Photograph 5 - Left Main Landing Gear Grass Impression Toward VASI Light (Courtesy of FAA)



Photograph 6 - Left Main Landing Grass Impression And Contact With VASI Light (Courtesy of FAA)



Photograph 7 - Left Main Landing Gear Rim Damage And Deflated Tire (Courtesy of FAA)



Photograph 8 - Composite Left Wing Damage (Courtesy of FAA)



Photograph 9 - Underside View of Composite Left Wing Damage (Courtesy of FAA)