

ERA26LA261

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Left Elevator Damage (Courtesy of FAA)