

ERA26LA264

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right wing leading edge damage (Courtesy of FAA)



Photograph 2 -Right wing leading edge damage (Courtesy of FAA)