

ERA26LA280

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of the airplane at the accident site. (Courtesy of Airport Manager)**



**Photograph 2 - View of damage to the lower left wing and aileron. (Courtesy of FAA)**





**Photograph 3 - View of damage to the lower left wing. (Courtesy of FAA)**



**Photograph 4 - View of the left main landing gear. (Courtesy of FAA)**



**Photograph 5 - View of the right main landing gear. (Courtesy of FAA)**



**Photograph 6 - View of the landing gear axles. (Courtesy of FAA)**