

ERA26LA284

INVESTIGATION PHOTOGRAPHS



Photograph 1 - left wing damage (Courtesy of FAA)



Photograph 2 - Left wing leading edge (Courtesy of FAA)



Photograph 3 - Left wing leading edge (Courtesy of FAA)