

ERA26LA301

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage With Vertical Stabilizer Damage (Courtesy of FAA)



Photograph 2 - Left Wing Damage (Courtesy of FAA)