



Photo 1 – View of substantial damage to tail pylon, main rotor and tail rotor blades