



Photo 1 – View of right side of airplane depicting where substantial damage to fire wall occurred (Courtesy of FAA)



Photo 2 – View of substantial damage to horizontal stabilizer (Courtesy of FAA)