



Photo 1 –View of left wing damage (photo courtesy of the FAA)



Photo 2 -View of empennage damage (photo courtesy of the FAA)