



Photo 1 – View of substantial damage to vertical stabilizer and rudder (Courtesy of FAA)



Photo 2 – View of substantial damage to fuselage and left inboard wing (Courtesy of FAA)



Photo 3 – View of damage to outboard right wing (Courtesy of FAA)



Photo 4 - View of right tire skid marks (Courtesy of FAA)



Photo 5 - View of left tire skid marks (Courtesy of FAA)