



Photo 1 – Left wing leading edge impact damage after colliding with trees (Courtesy of FAA)