



Photo 1 – View of damage to vertical stabilizer and rudder (Courtesy of FAA)



Photo 2 – View of damage to left wing spar (Courtesy of FAA)



Photo 3 – View of initial impact point (Courtesy of FAA)