



Photo 1 – View of the empennage and substantial damage (Photo courtesy of FAA)