



Photo 1 – View of substantially damaged windscreen and right wing lift strut (photo courtesy of FAA)