



Photo 1 – View of damage to right wing rib and spar (Courtesy of FAA)



Photo 2 – View of light pole distance from asphalt (Courtesy of FAA)