



Photo 1 – View of damage to the canopy and right side of empennage (Courtesy of Kathryn's Report)