



Photo 1 – View of damaged empennage (photo courtesy of the FAA)