



Photo 1 – View of damaged right aileron (photo courtesy of the FAA)




Photo 2 - View of damaged fuel line (photo courtesy of the FAA)