



Photo 1 – View of inverted glider with damage to right wing and empennage (Courtesy of FAA)



Photo 2 – View of damage to both wings and empennage (Courtesy of FAA)