



Photo 1 –View of right side fuselage separation (Courtesy of the FAA)



Photo 2 – Left wing leading edge damage (Courtesy of the FAA)



Photo 3 – Left wing trailing edge and aileron damage (Courtesy of the FAA)



Photo 4 – Left landing gear attach bolt (Courtesy of the mechanic)



Photo 5 – Torn left landing gear support and gear leg (Courtesy of the mechanic)