



Photo 1 – View of damage to engine mounts (Courtesy of FAA)



Photo 2 – View of damage to left wing strut (Courtesy of FAA)