



Photo 1 – View of right aileron damage (photo courtesy of the FAA)



Photo 2 – View of fuselage damage (photo courtesy of the FAA)



Photo 3 – View of empennage damage (photo courtesy of the FAA)