



Photo 1 – View of damage to vertical stabilizer (Courtesy of Operator)



Photo 2 – View of damage to aft canopy (Courtesy of Operator)