



Photo 1 – View of airplane inverted (photo courtesy of the FAA)



Photo 2 – View of damaged wing struts (photo courtesy of the FAA)