



Photo 1 – Substantial Damage to Left Wing (Photo Courtesy of FAA)



Photo 2 – Rubber Foot Pedal Next to Rudder Pedal (Photo Courtesy of Operator)