

Dear Mr Vanover,

I have attached the form 6120 for you .We are still evaluating the extent of the damage but as it stands we will at least be replacing all five main rotor blades ,the rotor hub and dampers along with the main drive shaft and parts of the landing gear. On most of the components the damage is magnetic not physical .There was no impact and no sudden stoppage . I will keep you updated as the inspection moves along.

If you have any questions please don't hesitate to contact me .

Best regards Jonathan



Jonathan Sole
Vice President of Operations
Air2 LLC