



Photo 1 – View of damage to the leading edge of the main rotor blade (photo courtesy of the operator).



Photo 2 - View of damage to the trailing edge of the main rotor blade (photo courtesy of the operator).