



Photo 1 – View of lower right wing damage (photo courtesy of the FAA)



Photo 2 – View of lower right wing aileron damage (photo courtesy of the FAA)