



Photo 1 – View of damage to leading edge tube (Courtesy of FAA)



Photo 2 - View of left/good side washout strut and split ring (Courtesy of FAA)