



Photo 1 – View of damaged right wing (photo courtesy of recovery company)



Photo 2 – View of damaged left wing (photo courtesy of recovery company)