



Photo 1 – View of damaged empennage and right wing (Photo courtesy of the FAA)